**Real Charge**
Record the real Kg / Lb of your blast.

2D / 3D View
See your boreholes pattern on 2D/3D view.

Projects
See all your projects and blasts.

Geometric Parameters
Control and register all the geometric parameters.

Real Coordinates
Add new boreholes to your pattern.

Water Presence
Record the presence of water or other KPI in each hole.

o-pitblast mobile application